



PROJECT UPDATE 8/11/2020



ARCHITECTURE
+ DESIGN



TWO WEEK LOOK AHEAD

- ▶ Electric rough
 - ▶ Sprinkler rough
 - ▶ Exterior framing
 - ▶ Roof installation
 - ▶ Exterior boarding
 - ▶ Plumbing rough
- 
- A decorative graphic consisting of several parallel white lines of varying lengths, slanted diagonally from the bottom right towards the top right, set against a blue gradient background.

August	Impact	Precip	High temp
1	0	0.57	85
2	0	0.01	81
3	0	0.12	83
4	0	0	79
5	0	0	79
6	0	0	80
7	0	0	82
8	0	0	89
9	0	0	89
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
21			
22			
23			
24			
25			
26			
27			
28			
29			
30			
31	0	0	



10= Weather day

5 day impacted by previous day

0 Workable day on site

3 half day wind for iron work

4 half day rain



Weather days to date

Feb	21
Mar	2
April	2
May	4
June	0.5
July	2
August	0
Total	31.5

SHAREFAX WEATHER LOG

Sharefax Open RFI Log

Item #	Date	Sub	Description	Returned	Response	Distributed	Status
42	7/23/20	HBC	Piping for booster pump				

SHAREFAX OPEN RFI'S


Sharefax Credit Union Potential Change Order Request Open Items

Item #	Date	Description	Cost Estimate	Issue type	Resolution	Date	Status
3	3/3/20	Revisions to sanitary sewer	-\$7,000	Clermont County			Open
12	5/4/20	Additional steel per light guage metal framing drawings	TBD	Owner request			Open
13	5/4/20	Revisons to handrails on balcony	TBD				Open
14	6/8/20	Revisons to handrails at drive thru	TBD	Drawing clarification			Open
15	6/3/20	Brick ledge on 3rd floor	TBD	Drawing clarification			Open
Total			\$55,220				

SHAREFAX OPEN PCO ITEMS



BUILDING LOOKING NORTH





BUILDING LOOKING SOUTH





BUILDING LOOKING EAST






BUILDING LOOKING WEST





FIRST FLOOR LOOKING NORTH






FIRST FLOOR LOOKING SOUTH





SECOND FLOOR LOOKING NORTH






SECOND FLOOR LOOKING SOUTH



OPEN OFFICE 229 LOOKING WEST






THIRD FLOOR LOOKING NORTH







THIRD FLOOR LOOKING SOUTH





FOURTH FLOOR LOOKING NORTH






FOURTH FLOOR LOOKING SOUTH



OFFICE 411 LOOKING WEST



LIGHTNING PROTECTION INSTALLATION





FRAMING
INSTALLED FOR
SIGNAGE ON THE
WEST SIDE OF THE
BUILDING

SITE LOOKING EAST

